UNCLASSIFIED AD 411838

DEFENSE DOCUMENTATION CENTER

FOR

SCIENTIFIC AND TECHNICAL INFORMATION

CAMERON STATION. ALEXANDRIA. VIRGINIA



UNCLASSIFIED

NOTICE: When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

411838

Rock Island Arsenal Laboratory





TECHNICAL REPORT

MULTIMETAL COATING PROCESS FOR COMPOSITE STEEL, MAGNESIUM, AND ALUMINUM STRUCTURES

Ву

Jodie Doss

Department of the Army Project No. 1-H-Q-24401-A-110

AMC Code No. 5026.11.842

Report No. 63-1651

Copy No. 1-9-100-2

Date 16 May 1963

DISTRIBUTED BY THE OFFICE OF TECHNICAL SERVICES U. S. DEPARTMENT OF COMMERCE WASHINGTON 25, D. C.

THIS REPORT MAY BE DESTROYED WHEN NO LONGER REQUIRED FOR REFERENCE

The findings in this report are not to be construed as an official Department of the Army position.

"Copies Available at Office of Technical Services \$ ___50 ".

Repor	t	No.	63-1651
Сору	No		

MULTIMETAL COATING PROCESS FOR COMPOSITE STEEL, MAGNESIUM, AND ALUMINUM STRUCTURES

Jodie Doss

Approved by:

Q. C. Hanson
Laboratory Director

16 May 1963

DA Project No. 1-H-0-24401-A-110

AMC Code No. 5026.11.842

Rock Island Arsenal Rock Island, Illinois

DDC Availability Notice

Qualified requesters may obtain copies of this report from DDC.

ABSTRACT

Aluminum, steel and magnesium trimetal assemblies were simultaneously coated in order to decrease galvanic corrosion and to develop coatings to be used for recoating structurally united components containing dissimilar metals. The following experimental solutions were utilized to coat trimetal assemblies: stannate-chromate, phosphate, stannate-gluconate, stannate-hypophosphate, and stannous pyrophosphate. The stannous pyrophosphate solution produced the best coatings on the assemblies.

RECOMMENDATIONS

The developed coatings from the stannate-chromate solution and the stannous pyrophosphate solution should be further investigated for use on Army material.

Other coatings for multimetal assemblies should be developed and investigated.

11

MULTIMETAL COATING PROCESS FOR COMPOSITE STEEL, MAGNESIUM, AND ALUMINUM STRUCTURES

CONTENTS

	Page No.
OBJECT	1
INTRODUCTION	1
PROCEDURE AND RESULTS	3
Materials	3
Stannate Solutions:	3
Chromate	3
Pyrophosphate-Fluoride	5
Ethylenediamine Tetraacetate, Disodium	6
Gluconate	6
Hypophosphite	6
Stannous Solutions:	8
Pyrophosphate	8
Phosphate Solutions:	9
DISCUSSION	9
LITERATURE REFERENCES	11
DISTRIBUTION ·	12

MULTIMETAL COATING PROCESS FOR COMPOSITE STEEL. MAGNESIUM. AND ALUMINUM STRUCTURES

OBJECT

To find a coating for composite steel, magnesium and aluminum.

INTRODUCTION

Since weight is a very important consideration in the design of rockets and missiles, light metals such as aluminum and magnesium are utilized in their construction. Certain components still must be fabricated of steel where construction requirements dictate this metal.

The three metals structurally united into rockets or missiles components create two problems of major importance. The two problems are:

- Galvanic cells leading to galvanic corrosion (See Figure 1a).
- 2. Coating, to prevent galvanic corrosion without destroying one or more of the dissimilar metals in the assembly.

McKay and Worthington⁽¹⁾ define galvanic corrosion as the corrosion of a metal due to it being electrically connected to another metal in a corrosive condition. Such a cell is composed of four parts. The four parts are the anode, cathode, electron conductor and continuous liquid path⁽²⁾ Corrosion occurs at the anode. If one of the four parts of a galvanic cell is missing, galvanic corrosion will not occur.

Reichhard⁽³⁾ states that metals are either anodic or cathodic, with respect to other metals with which they are associated. No metal has an absolute or inherent value of potential. Potential is a relative property. The potential of a metal is determined by the environment and the specific metal or metals used as a basis of comparison.

The greater the potential difference between metals, the greater the galvanic corrosion. When the potential between metals is small, the electrolyte employed determines which metal becomes the anode. (4) Coupled magnesium and aluminum exhibits a small potential, therefore, the galvanic corrosion is not great. When magnesium or aluminum is coupled with steel, the potential is relatively great.

Therefore, when steel is united with one or both of these metals in the presence of moisture, galvanic corrosion occurs.

Galvanic corrosion can be reduced in many ways. These include:

- a. Decreasing the potential by combining metals that are close in nobility, such as magnesium and aluminum.
- b. Using cathodic fasteners which result in large anodic area, in relation to cathodic area.
 - c. Insulation of dissimilar metals.
 - d. Polarization (passiviation) of one of the metals.
 - e. Painting both metals.
- f. Using corrosion inhibitors such as chromates in aqueous solution. (5)
 - g. Using sacrificial anodes.
- h. Using metallic coatings to reduce contact potential of dissimilar metals. (6)

The coating of multimetal assemblies containing aluminum, magnesium and steel components to decrease galvanic corrosion creates problems. It is frequently impossible to separate the multimetal assemblies without destroying the multimetal component. It is therefore, necessary to provide a means of coating all three metals in the component simultaneously.

In coating the trimetal assemblies, one must be cognizant of the fact that alkaline solutions for coating would attack and destroy the aluminum, while acid solutions for coating would attack and destroy the magnesium. Several approaches to the problem, based upon formation of metallic coatings, appeared to offer promise of success.

It was found, during investigations of various metallic coatings for compatibility with magnesium, that tin was superior to all other metals. Some tin alloys were also good. The tin compounds were superior to cadmium and zinc on steel. Tin coatings over aluminum alloys also reduced trimetallic couple (galvanic) corrosion. (7)

Investigations were initiated utilizing solutions for tin coatings alone or coatings containing tin plus other compounds.

PROCEDURE AND RESULTS

Materials

The aluminum materials used in the investigation were listed under Federal Specification QQ-A-561, 1100(2S) and QQ-A-318, 5052(52S). The magnesium alloy was QQ-M-44,AZ31B.

Panels were prepared from the sheet metals in the following size, $2" \times 3" \times 0.0625"$ with 1/4" holes drilled through the center. The two aluminum and magnesium panels were securely fastened together with the major dimensions at right angle to each other, by means of a 1/4" round head steel machine screw and nut, as shown in Figure 1.

The composite specimens were degreased, utilizing a trichloroethylene vapor degreaser, prior to processing.

The following processing solutions were prepared and subsequently evaluated.

Stannate Solutions:


Chroma te

A solution was prepared as shown below:

20 grams Na₂CO₃.H₂O
1 gram K₂Cr₂O₇
50 grams Na₄P₂O₇.10H₂O
50 grams Na₂SnO₃.3H₂O
Enough water to make 1 liter of solution.

This solution was heated to 195 ± 5°F. A composite trimetal assembly was submerged in the solution for thirty minutes. Upon removing the composite specimen from the solution, it was observed that a conversion coating had formed on the surface of the aluminum. Tin coatings appeared to be on the surface of the magnesium and steel (see Figure 1b). The same results were obtained with a second trimetal assembly. The addition of ten grams of sodium acetate to the solution improved the subsequent coatings. A trimetal assembly was coated in the chromate-stannate solution and submerged for ten minutes in a near boiling, 5% potassium, dichromate sealing solution, water rinsed and air blown dry. The coatings had a yellow, tinted color.

Two coated trimetal assemblies were separated and exposed, along with uncoated separated trimetal assemblies, in a 5% salt fog cabinet for corrosion resistance tests. The



TYPE OF TRIMETAL ASSEMBLIES USED IN THIS INVESTIGATION
Vertical Panels are Aluminum, Horizontal Panels are Magnesium
Bolts and Nuts are Steel

salt fog cabinet was operated in accordance with Method 811.1 of Federal Test Method Standard No. 151.

The test specimens were inspected after 2.5 hours. The uncoated steel had rusted. The uncoated magnesium specimen had a large amount of corrosion products on the surface. The apparently tin coated magnesium specimens had some corrosion present.

After 19 hours exposure the apparently tin coated steel screw and nut had a small amount of rust present. All the magnesium specimens (coated and uncoated) were very corroded. They were removed from further testing.

After 192 hours, the aluminum panels, believed to be coated with a chromate coating, had a small amount of white corrosion products present. The uncoated aluminum panels were dark with white corrosion products. The salt fog test was terminated.

It was found that the stannate-chromate solution would coat bimetal assemblies of steel and aluminum, steel and magnesium, aluminum and magnesium, but not steel alone. It was believed that a chromate coating was present on the aluminum and a tin coating was formed on the steel and magnesium. These coating were noted after treatment in the solution, and verified by comparison with the untreated panels after exposure in the salt fog cabinet.

It was learned that the prepared stannate-chromate solution would coat the trimetal assemblies, however, the coating on the aluminum 1100 alloy was not entirely satisfactory. It was subsequently determined, through further work, that the following solution would satisfactorily coat the alloys in the trimetal assembly.

20 grams Na₂CO₃.H₂O

2 grams K2Cr207

20 grams Na₄P₂O₇.10H₂O

50 grams Na₂SnO₃.3H₂O

Enough water to make a one liter solution.

The above solution was operated at 195 \pm 5°F.

Stannate solutions containing compounds other than chromates were prepared and attempts were made to coat the trimetal assemblies.

Pyrophosphate-Fluoride

The first solution contained sodium pyrophosphate and

potassium fluoride. Trimetal assemblied were processed in this solution at 180 to 190°F for twenty minutes. The pH of the solution was adjusted between 9.6 - 11.0. No satisfactory coating was obtained on any of the metals in the trimetal assemblies. The coatings were either very thin or nonadherent.

Ethylenediamine Tetraacetate, disodium

The second solution contained the disodium salt of ethylenediamine tetraacetic acid. The pH of the solution was adjusted to 10.3 with the acid salt. The solution was operated at 180 to 190°F. No satisfactory coating was obtained on any of the metals in the trimetal assembly. The coatings were either very thin or nonadherent.

Gluconate

The third solution contained sodium gluconate. The solution pH was reduced from 10.3 to 9.6 with ethylenediamine tetraacetic acid. The initial temperatures of the solution was 180 to 190°F, and then reduced to the final temperature of 140 to 150°F. Satisfactory coatings were obtained when the pH of the solution was 9.6 and the temperature of the solution was 140 to 150°F. There was an apparent bright tin coating on the steel and aluminum and a dull tin coating on the magnesium (see Figure 1°C.)

The solution composition was as follows:

50 grams sodium stannate

50 grams sodium gluconate

Water to make 1 liter

This solution also coated the individual aluminum and magnesium specimens. The addition of 7 grams, per liter, of potassium fluoride to the solution improved the quality of coating on the magnesium in the trimetal assembly.

Hypophosphite

The fourth solution contained sodium hypophosphite. The solution was prepared as follows:

30 grams sodium stannate Na₂SnO₃.3H₂O
10 grams sodium hypophosphite NaH₂PO₂.H₂O
Water to make 1 liter

The pH of the solution was adjusted to 9.5 with ethylenediamine tetraacetic acid. The solution was maintained at room temperature. Processing time was twenty minutes. A heavy, bright, apparent tin coating was deposited on all three of the metals in the trimetal assembly. The solution coated steel plus aluminum, steel plus magnesium, magnesium and aluminum individually, but not steel alone. Two trimetal assemblies were tested in the salt spray (5%). There was very little galvanic corrosion after an 8 hour exposure.

Other compounds utilized as pH depressors, instead of ethylenediamine tetraacetic acid, were gluconic acid, boric acid and glycolic acid. The utilization of glycolic acid in the stannate solution produced a satisfactory coating on the trimetal assembly. The coating was thick and adhered to the basis metal.

The stannate-hypophosphite solution contained a large amount of sludge. It was also necessary to add, after each processing of trimetal assembly, a small amount of ethylene-diamine tetraacetic acid to control the pH of the solution.

It was found that the following solutions performed satisfactorily without close process centrol:

10 grams sodium stannate

5 grams sodium hypophosphite

Water to make 1 liter

Initial pH of solution 11.2

The pH of the above solution was adjusted to 9.5 with 5 to 6 grams of ethylenediamine tetraacetic acid and 1 to 2 grams of boric acid. This solution was relatively free of sludge and the pH remained rather constant. The addition of one gram of $A1(NO_3)_3$ to the solution improved the coating on the aluminum.

Trimetal assemblies previously used were cleaned to remove the deposited coatings. They were immersed in an alkaline solution containing 22 gms. sodium carbonate, 22 gms. trisodium phosphate/liter solution at 190°F for two minutes, water rinsed and rinsed in an 8% HNO3 solution. They were immediately water rinsed and placed in the stannate solution for processing.

Difficulty was encountered with rusting of the steel portion of the component after the acid dip and prior to the coating operation.

This problem was partially overcome by the addition of a small amount (.01% solution) of I_2 -KI to the nitric acid

solution. The stannate-hypophosphite solution was not coating the cleaned steel, but heating of the processing solution to 150 \pm 5°F partiall overcame this problem.

Stannous Solutions:

Pyrophosphate

A formula for a stannous pyrophosphate plating solution $\binom{8}{8}$ was modified in order to tin coat, by immersion, trimetal assemblies. The composition of the modified solution was as follows:

* 50 grams SN₂P₂O₇
50 grams Na₄P₂O₇.10H₂O
10 grams dextrine
1 gram gelatin
Enough water to make a one liter solution.

The pH of the solution was 6.2. The solution was operated at $195 \pm 5^{\circ}$ F. The trimetal assemblies were immersed in the solution for thirty minutes, water rinsed and air dried. There was a thick adherent shiny tin coating on the aluminum and steel of the trimetal assemblies (see Figure 1). There was a dark grey coating on the magnesium component.

The pH of the solution was still 6.1 after four or five processing cycles.

The resistance to corrosion, including galvanic corrosion, was better than that of the other coatings. Galvanic corrosion was first noticed after 2 hours exposure to salt spray.

This processing solution would coat any two metal combinations or aluminum and magnesium separately, but not steel separately.

The Sn₂P₂0₇ solution was prepared as follows: 198 gms. of SnCl₂ was added to 500 ml. of distilled water with constant agitation. Conc. HCl was added to the solution until all the SnCl₂ was dissolved. This solution was poured into an aqueous solution of 196 gms. of Na₄P₂O₇.10H₂O and made up to one liter. The resultant solution was stirred and filtered by suction through a 41H filter paper. The precipitate was washed four or five times with distilled water and subsequently dried in an oven at 230°F. Changes in the pH of the solution produces different coatings as follows:

pH 6.0 (by addition of H₃PO₄ solution)

Aluminum - Conversion type coating Steel - Shiny tin coating Magnesium - Conversion type coating

pH 7.0 (by addition of 5% NaOH solution)
Aluminum - Very bright shiny tin coating
Steel - Very bright shiny tin coating
Magnesium- Thick adherent conversion type coating.

pH 8.0 (by addition of 5% NaOH)
Aluminum - Shiny tin coating
Steel - Shiny tin coating
Magnesium- Dull tin coating

Phosphate Solutions:

A zinc phosphating solution, that was accelerated and buffered to coat steel at room temperature, was used for coating the trimetal assemblies. It was found that if the phosphating solution was heated to $200 \pm 5^{\circ} F$ it would phosphate coat all three of the steel grit blasted metals in trimetal assemblies. The processing time was thirty minutes. The phosphate coating on the magnesium metal had numerous grey spots. The addition of 3 - 5 grams AlCl₃ per liter of solution either eliminated or decreased the size of the spots in subsequently produced phosphate coatings.

The phosphate coated trimetal assemblies were immersed in a near boiling five percent dichromate solution for ten minutes. There was no noticeable change in the coating.

It was necessary to adjust the pH of the phosphating solution after each processing of trimetal assemblies.

DISCUSSION

The 1100 aluminum sheet contained a minimum of 99 percent aluminum. The 5052 aluminum is an aluminum alloy containing magnesium as the major alloying metal. The magnesium sheet contained 3 percent aluminum and one percent zinc.

The stannate-chromate solution was a combination of the major chemicals found in some chemical processes for aluminum and magnesium. The solution coated the aluminum with a chromate conversion coating that appeared to be as good as a commercial chemical process for aluminum. The solution coated the magnesium with an apparent tin coating that appeared to be as good as an immersion tin process for magnesium (see Figure 1b). The first solution developed would not satisfactorily coat the 1100 aluminum, probably because the galvanic potential between the 1100 aluminum and magnesium was not as great as the 5052 aluminum and magnesium. Modification of the solution eliminated this problem.

The phosphating of the trimetal assemblies produced a good paint base coating. The phosphate coatings did not improve the galvanic corrosion resistance of the trimetal assemblies. In fact, the phosphate coating in the presence of salt fog seemed to increase the galvanic corrosion. Examination of the phosphate coated trimetal assemblies, upon removal from salt fog, revealed a visual chemical reaction on the surface of the magnesium component.

The stannate-gluconate and the stannate-hypophosphite solutions produced good coatings on the trimetal assemblies (see Figure 1). The pH of the solutions had to be maintined within a narrow range, or the coatings would be inferior or no coatings were produced either on the magnesium or aluminum. Stannate solutions are not as stable as the following pyrophosphate solution.

The stannous pyrophosphate solution was very stable. The coatings adhered well to the metals (see Figure 1d). The solution coated trimetal assemblies over a wide pH range and coated well in recess areas. Coated trimetal assemblies exhibited good galvanic corrosion resistance. The pH of the solution can be maintained at neutral or near neutral (pH 7 to 8), thereby eliminating attacks on the metals in the trimetal assemblies during processing.

LITERATURE REFERENCES

- 1. McKay, J. M. and Worthington, R., "Corrosion Resistance of Metals and Alloys," Reinhold Publishing Corporation, New York, 1936.
- 2. Stevens, J. A., "Designing for Long Service: A Primer Of Magnesium Finishing," Magnesium Topics, 8, 12, 1958.
- 3. Reichard, E. C., "Control Galvanic Corrosion Stop Costly Failures," Materials and Methods, 83-6, Aug. 1952.
- 4. Evans, U. R., "Metallic Corrosion Passivity and Protection," Longmans, Green and Company, London, 1946.
- 5. "The Corrosion Handbook," edited by Uhlig, Herbert H., John Wiley and Sons, Inc., New York, 1948.
- 6. Reinhart, F. M., "Corrosion Factors in Design," Product Finishing, pp. 101-7, July 1951.
- 7. "Protective Coatings on Magnesium Alloys Intended for Use on Components of Airborne Vehicles," Dow Chemical Co., Dept. of Army Contract No. DA-20-018-ORD-15406, 1957 1958.
- 8. Vaid, J. and Ramer. Char, T. L., Journal of Electrochemi⇒ cal Society, 104, 5, 286, May 1957.

		No. of Copies
Α.	Department of Defense	
•	Office of the Director of Defense	
	Research & Engineering	
	ATTN: Mr. J. C. Barrett	
	Room 3D-1085, The Pentagon	
	Washington 25, D. C.	1
	Commander	•
	Defense Documentation Center ATTN: TIPDR	
	Arlington Hall Station	
	Arlington 12, Virginia	20
В.	Department of the Army - Technical Service	S
		_
	Commanding General	
	U.S. Army Materiel Command	
	Room 2502, Bldg. T-7	
	ATTN: AMCRD-RS-CM	•
	Washington 25, D. C.	1
	Commanding Officer	
	U.S. Army Chemical & Coating Laboratory	•
	ATTN: Dr. C. Pickett	1
	Technical Library	1
	Aberdeen Proving Ground, Maryland	
	Commanding General	
	U.S. Army Tank Automotive Center	
	ATTN: SMOTA-REM.2	1
	SMOTA-REM.3	1
	Warren, Michigan	
	Commanding General	
	U.S. Army Weapons Command	,
	ATTN: AMSWE-RD	1 1
	AMSWE-PP Rock Island Arsenal	1
	Rock Island, Illinois	
	MOON TOTAIN, TITINGTO	

	No. of Copies
Commanding General	
U.S. Army Missile Command	
ATTN: Documentation & Technical	
Information Branch	2
Mr. R. E. Ely, AMSMI-RRS	1
Mr. R. Fink, AMSMI-RKX	1
Mr. W. K. Thomas, AMSMI	1
Mr. E. J. Wheelahan, AMSMI-RSM	1
Redstone Arsenal, Alabama	
Commanding Officer	
Frankford Arsenal	
ATTN: SMUFA-1330	1
Library-0270	1
Philadelphia 37, Pa.	
Commanding Officer	
U.S. Army Materials Research Agency	
Watertown Arsenal	
ATTN: RPD	
Watertown 72, Massachusetts	1
Commanding Officer	
Picatinny Arsenal	
ATTN: Plastics & Packaging Lab	
Dover, New Jersey	1
Commanding Officer	
PLASTEC	
Picatinny Arsenal	
Dover, New Jersey	1
Commanding Officer	
Springfield Armory	
ATTN: SWESP-TX	
Springfield 1, Mass.	1
Commanding Officer	
Watertown Arsenal	_
ATTN: SMIWT-LX	1
Watertown 72, Mass.	

	No. of Copies
Commanding Officer Watervliet Arsenal ATTN: SWEWV-RDR Watervliet, New York	1
Commanding General U.S. Army Munitions Command Dover, New Jersey	1
Commanding Officer U.S. Army Environmental Health Laboratory Army Chemical Center, Maryland	1
Commanding Officer Harry Diamond Laboratory ATTN: Technical Library Washington 25, D. C.	1
Commanding Officer Engineer R & D Laboratory ATTN: Materials Branch Ft. Belvoir, Virginia	1
Commanding General Quartermaster R & D Command ATTN: Clothing & Organic Materials Division Natick, Massachusetts	on 1
Commanding Officer U.S. Army Prosthetics Research Laboratory Forest Glen, Maryland	1
Commanding Officer Headquarters U.S. Army Signal R & D Laboratory ATTN: Materials Branch Fort Monmouth, New Jersey	1
Department of the Army - Other Army Agencie	es
U.S. Army Reactor Branch Division of Reactor Development Atomic Energy Commission Washington 25, D. C.	1

14

		No. of Copies
	Commander U.S. Army Research Office Arlington Hall Station Arlington 12, Virginia	1
	Commanding Officer U.S. Army Research Office (Durham) Box CM, Duke Station Durham, North Carolina	, 1
	Chief of Research & Development U.S. Army Research & Development Liaison Group ATTN: Dr. B. Stein APO 757	
	New York, N. Y.	1
c.	partment of the Navy	
	Chief, Bureau of Naval Weapons Department of the Navy ATTN: RMMP Room 2225, Munitions Building	
	Washington 25, D. C.	1
	Commander Department of the Navy Office of Naval Research ATTN: Code 423 Washington 25, D. C.	1
	Chief	
	Department of the Navy Bureau of Ships ATTN: Code 344 Washington 25, D. C.	1
	Commander Department of the Navy Special Projects Office ATTN: SP 271	1
	Washington 25, D. C.	1
	Commander U.S. Naval Ordnance Laboratory ATTN: Code WM	
	White Oak Silver Spring, Maryland	1
	15	63-1651

		No. of Copies
	Commander U.S. Naval Ordnance Test Station ATTN: Technical Library Branch China Lake, California	1
	Commander U.S. Naval Research Laboratory ATTN: Technical Information Center Anacostia Station Washington 25, D. C.	1
	Commander Mare Island Naval Shipyard ATTN: Rubber Laboratory Vallejo, California	1
D.	U.S. Air Force Directorate of Research and Development ATTN: Lt. Col. J. B. Shipp, Jr. Room 4D-313, The Pentagon Washington 25, D. C.	1
	Commander Wright Air Development Division ATTN: ASRCEE-1 WWRCO Materials Central Wright-Patterson Air Force Base, Ohio	1 1 1
	6593 Test Group (Development) ATTN: Solid Systems Division, DGSC Edwards Air Force Base, California	1
	Commander AMC Aeronautical Systems Center ATTN: Manufacturing & Materials Technology Division, LMBMO Wright-Patterson Air Force Base, Ohio	2

16

		No. of Copies
E.	Other Government Agencies	
	Scientific & Technical Information Facility	
	ATTN: NASA Representative (S-AK/DL) Mr. B. G. Achhammer	. 1 . 1
	Mr. G. C. Deutsch	ī
	Mr. R. V. Rhode	1
	P. O. Box 5700	
	Bethesda, Maryland	
	George C. Marshall Space Flight Center	
	ATTN: M-S&M-M	1
	M-F&AE-M	1
	Huntsville, Alabama	
	Jet Propulsion Laboratory	
	California Institute of Technology	
	ATTN: Dr. L. Jaffe	
	4800 Oak Grove Drive	_
	Pasadena, California	1
	Commanding General	
	U.S. Army Weapons Command	
	ATTN: AMSWE-RD	3
	Rock Island Arsenal	
	Rock Island, Illinois	
	for	
	release to	
	Commander	
	British Army Staff	
	ATTN: Reports Officer	
	3100 Massachusetts Avenue, N. W.	
	Washington 8, D. C.	
	Commanding General	
	U.S. Army Weapons Command	
	ATTN: AMSWE-RD	3
	Rock Island Arsenal	
	Rock Island, Illinois	
	for release to	
	Canadian Army Staff, Washington ATTN: GSO-1, A&R Section	
	ATTN: GSO-1, A&R Section 2450 Massachusetts Avenue, N. W.	
	Washington 8, D. C.	
	HESTITIE COT O, D. C.	

	No. of Copies
Prevention of Deterioration Center National Academy of Science Nationa Research Council 2101 Constitution Avenue	
Washington 25, D. C.	1
Office of Technical Services Stock 1200 South Eads Street	
Arlington, Virginia	100

UNCLASSIFIED 1. Chalings for Magnesium 2. Coalings for Alumnum 3. Coalings for Steel 4. The Coalings 5. Phosphate Coalings 10 ISTRIBUTION. Copies Ontainable from DDC.	UNCLASSIFIED 1. Coatings for Magnesium 2. Coatings for Aluminum 3. Coatings for Steel 4. Tip Coatings 5. Phosphate Coatings 6. Distribution: 1. Copies obtainable Copies obtainable from DDC
ACCESSION NO. ROCK ISLAND ARSENAL LABORATORY, ROCK ISLAND. JULIOLS. MULTIMETAL COATING PROCESS FOR COMPOSITE STEEL, MAGNESIUM, AND STEEL STRUCTURES. by JOGIE DOSS RIA LAD. Rep. 63-1651, 16 May 63, 18 p. incl. JULIA, tables, (DA Project No. 1-H-O-24401-A- 110. AMC Code No. 5026.11.642) Unclassified report. Aluminum, steel and magnesium trimetal assembles ere simulatorously coated in order to decrease galvanic corrosion and to develop coatings to be used for recoating structurally united components containing dissmilar metals. The iollowing experimental solutions were chromate, phosphase ramnate and stannate stannate— thromate, phosphase ramnate stannate stannate— has tannous pyrophosphase. The stannous pyrophosphase. The stannous pyrophosphase.	Accession No. Rock Island Argenal Laboratory, Rock Island, Illinois. WULTIMETAL CONTING PROCESS FOR COMPOSITE SIEEL, MAGNESIUM, AND STEEL STRUCTURES, by Jodie Does RIA Lab. Rep. 63-1651, 16 May 63, 18 p. incl. Illus., tables, (Na Project No. 1-R-0-24601-A- Illo, AMC Code No. 5026.11.842) Unclassified report. Alumbum, steel and magnesium trimetal assemblies were simultaneously coated to order to decrease galvanic corrosion and to develop coatings to be used for recenting structurally united components containing dissimilar metals. The following experimental solutions were utilized to cost trimeral assemblies: stanmate- chromate, phosphate, stanmate-glucomate, stan- mate-bypophosphate, stanmate-glucomate, stan- the stanmous pyrophosphate solution produced the best coatlure on the massmallas.
UNCLASSIFIED 1. Coatings for Magnesium 2. Coatings for Aluminum 3. Coatings for Steel 4. Tin Coatings 5. Phosphate Coatings 6. Phosphate Coatings from DDC.	1. Coatings for Magnesius 2. Coatings for Alusius 3. Coatings for Steel 4. Tin Coatings 5. Phosphate Coatings Coatings for Coatings for Steel from DDSTRIBUTION.
ROCK ISLEDG AFBERS! Laboratory, Rock Island, Illinois. MULTIMETAL COATING PROCESS FOR COMPOSITE STEEL, MAGNESIUM, AND STEEL STRUCTURES, by Jodie Doss Ria Lab. Rep. 63-1651, 16 May 63, 18 p. incl. illus., tables, (DA Project No. 1-R-0-24401-A-110, AMC Code No. 5026.11.842) Unclassified report. Alumanum, steel and magnesium trimetal massemblis and components contains contains develop coatrags to be used for recoating structurally united components containing distaining structurally united components containing distaining structurally united components containing structurally. The following experimental assemblies: Stannate-office and the stannous pyrophosphate, stannate-gluconate, stannate-bypophosphate, and stannous pyrophosphate. The stannous pyrophosphate solution produced the best coatings on the assemblies.	ACCESSION NO. ROCK ISLEND Arsebal Laboratory, Bock Island, Illinois. Illinois. MAGNESIUM, AND STEEL STRUCTURES, by Jodie Dose RIA Lab. Rep. 63-1631, 16 May 63, 18 p. incl. 131us., tables, (DM Project No. 1-H-O-24401-A- 110. AMC Code No. 5026.11.842) Unclassified report. Aluminum, steel and magnesium trisetal assemblate were simultaneously comted to develop contrings to be used for recomiting structurally united components containing dissimilar metals. The following experiments solutions were chromate, pnosphate, and stamnate-glucomate, stamnate- chromate, pnosphate, and stamnous pyrophosphate. The starrous pyrophosphate solution produced the fast coatings on the assemblies

•